


14hp L-series with front mounted exhaust cam driven water pump



Oil drain/Camshaft centre bearing feed



Extra stud holes in RRSL gasket are the result of cost savings from common tooling, now deleted on latest gasket?

